NAD C520/C521

MODIFICATION

PROBLEM:


You may receive a complaint of the unit producing a very high whistle noise

CAUSE:

The step up transformer for the display circuit is humming

SOLUTION:

- 1. Insert a transformer with more varnish impregnation
- 2. Apply glue to fix the step-up transformer to the main pcb
- **3.** Add double sided tape between the cushion at the back of the EL display and the front panel pcb. Please refer to the drawing below



PRODUCTION:

This modification will be implemented in production from serialnumber: G0ZC52107201



for C521/C541,C520/C540,C522/C524

If the cd player has a complaint of not able to play a cdr or out of tolerance discs, try replacing these capacitors with the following values. This will also provide a cure on some players for "NO DISC" message.

<u>C520/C521 /C522/C524</u>

C122 is changed to 2.7pF

C123 is changed to 0.01uF

C124 is changed to 22pF

<u>C540/C541</u>

C122 is changed to 2.7pF

C123 is changed to 0.01uF

C124 is changed to 22pF

C311 is changed to 220pF

Production:

This change has been implemented in production from serial number: G19C52113901 - C521/C G19C54108101 – C541/AH G19C54108401 – C541/C

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1 Voice: 905-831-0799 FAX 905-837-6357 www.nadelectronics.com