

Service Information L70

Circuit Change

PROBLEM: When using the component out on the L70 you may find the video signal has faint diagonal lines appearing.


CAUSE: The ground plane requires additional coupling.

SOLUTION: Add a 10 ohm resistor to location R593 on the video board.

Add a 0.1uF ceramic capacitor to location C593 on the

video board. See photo below.

Photo 1



PRODUCTION:

All production to September 2003 is affected.

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1 Voice: 905-831-0799 FAX 905-837-6357



Service Information L70

Circuit Change

PROBLEM: You may have the complaint that the TV SCART RGB output is not switching automatically.

CAUSE: The drive current of some television sets is not sufficient to switch the RGB output.


SOLUTION:

Delete RE31 100 ohm resistor on video board. Add a 10 ohm resistor between PIN 16 of SCART connector (one leg of RE31) and +5V rail(one leg of R554) on video board. See photo and schematic diagram.

Photo



Schematic



PRODUCTION:

All production to September 2003 are affected. Serial numbers to be advised.

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1 Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com

10/07/03



Technical Bulletin L70

Product: DVD Receiver
Hardware Technical Bulletin: L70-H2004-05

Date: June 21, 2004 Subject: Fan Kit Installation

Note:

Previous T.B.'s required:

□ YES

■ NO

DESCRIPTION: The small ventilation fan located on the DVD mechanism, is noisy or is turning too slowly.

REASON: The fan bearing is worn.

SOLUTION: Replace the existing fan with the following new fan and parts. This fan is located beside the DVD mechanism. Please note that removal of the dvd mechanism is required for this change. Note, this fan only runs when the dvd input is selected.

The fan kit can be ordered under the number: HDMKD1245PFS2

Kit includes:

Copal fan, fan bracket, CN89 Wafer

R922 82 OHMS (ORIGINALLY 100 OHMS) R951 91 OHMS (ORIGINALLY 100 OHMS)

- 1. As shown cut the supplied bracket in order to install it with the new fan.
- 2. Secure fan to the bracket and add some glue to the bottom of the bracket when securing to the chassis. See figure 1 and 2.

Figure 1



Cut bracket here

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com



Technical Bulletin L70

Product: DVD Receiver


Hardware Technical Bulletin: L70-H2004-05



Glue bottom of bracket to chassis

3. Replace R922 (100 ohms)and solder the 82 ohm resistor supplied, to one leg of the male plug and solder the other to capacitor C 905 + side. This is on the bottom of the main cpu pc board which mounts to the top of the dvd player mechanism.

Figure 3



R922 on bottom of pc board 100 ohm changes to 82 ohm.

Fan connector

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com



Technical Bulletin L70

Product: DVD Receiver


Hardware Technical Bulletin: L70-H2004-05

4. Glue connector to PCB as shown in figure4.

Figure 4



Figure 5



Right side of receiver

Towards Front panel

Contact:

NAD Electronics International 633 Granite Court

Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com