

Product: A/V Receiver

Hardware Technical Bulletin: T773-H2005-05R

Date: March 7/05

Subject: Static protection for muting transistors

Note: Implemented in production from serial number:R49T77302671

Previous T.B.'s required: Revised from T773-H2005-05

- YES
- NO


DESCRIPTION: You may have the complaint that the subwoofer or other channels are popping when switching inputs or when turning on and off.

REASON: The channel that is popping may have a muting transistor damaged due to an external source or subwoofer causing static damage to the transistor.

SOLUTION: Replace the transistor and install a 4700 pF capacitor between the base and collector on the pre amp pc board, as shown in the following two schematics. The use of a surface mount capacitor is recommended. Placing the capacitor on the bottom of the board between the base and collector of each muting transistor is preferred. See figure 2 on page 2.

Note: It is recommended to install this capacitor to each channel's muting transistor. The following are the designations of the muting transistors, Q608, Q609, Q610, Q611, Q612, Q613, Q615, Q617 and Multi source muting transistors Q632, Q633.


Figure 1



Product: A/V Receiver

Hardware Technical Bulletin: T773-H2005-05R

Figure 2



4700pF surface mount capacitor between base and collector pins of muting transistor on the pre amp pc board

Contact:
NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com



Technical Bulletin T773

Product: A/V Receiver

Hardware Technical Bulletin: T773-H2004-02

Date: June 1, 2004

Subject: HDTV Component
Video change

Note: Implemented in production from Serial number: R44 series and onwards

Previous T.B.'s required:

YES

NO

DESCRIPTION: To improve the compatibility of HDTV signals with some TV/Monitors.


REASON: When decoding HDTV signals some TV/Monitors may experience horizontal sync loss.

SOLUTION: Perform the following change to the Component video board.

On the component video PCB U4301

- A) Link the following pins on U4301;
- Pins 9 to 10
 - Pins 12 to 13
 - Pins 14 to 15

Figure1




Product: A/V Receiver

Hardware Technical Bulletin: T773-H2004-02

HDTV Component Video Change


B) Remove C4317, C4319, C4321.

Figure 2



C) Replace C4316, C4318, and C4320 with 1000 uF 6V.

Figure 3



Contact:

NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com

Product: A/V Receivers

Hardware Technical Bulletin: T773-H2004-03

Date: June 15, 2004

Subject: Flat Ribbon Cables

Note:

Previous T.B.'s required:

- YES
- NO

DESCRIPTION: *The unit may be experiencing intermittent audio or display. The unit may not always power up.*

REASON: *The flat ribbon cables, primarily the ones running from the front panel but may include all flat ribbon cables. They may have intermittent contact due to oxidization.*

SOLUTION: *Clean all ribbon connectors using an eraser or preferably a non alcohol based cleaner which will leave no residue. See figures 1, 2 and 3.*




Locate and remove the ribbon cables, front panel cables shown.

Figure 1


Product: A/V Receivers

Hardware Technical Bulletin: T773-H2004-03



Ribbon cables are easily unplugged from these connectors.

Figure 2



Clean the ends of the ribbon cables with eraser or non alcohol based cleaners.

Figure 3

Contact:
NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com



Technical Bulletin T773

Product: A/V Receiver

Hardware Technical Bulletin: T773-H2005-05

Date: February 28/05 **Subject:** Intermittantly shuts down
Note: Implemented in production from serial number:R44T77301971

Previous T.B.'s required:


- YES
- NO

DESCRIPTION: Unit may shut down, shortly after turn on.

REASON: There is a diode on the standby board that maybe operating intermittantly.

SOLUTION: Locate and identify D756 on the standby board. Change only if the diode is a 1N4148. Change from a 1N4148 to a 1N4004 or equivalent. See figure 1 for details.

Figure 1



D756
CHANGE
FROM
1N4148 TO
1N4004

Contact:
NAD Electronics International
633 Granite Court
Pickering, ON Canada L1K 3K1
Voice: 905-831-0799 FAX 905-837-6357
www.nadelectronics.com