

<b>marantz®</b>  <b>SERVICE BULLETIN</b>		Date: 15-May.-2003	Model: PM4200
		Page: 1 / 1	REF.NBR: MZ03-012
Circulation:	Application:	Subject: The unit works by the remote controller of other company.	
x for information customer complaint in case of service mandatory .....	See Below		
		Int.ref:	

#### [PHENOMENON]

Input Selector of PM4200 works by the remote control of DVR7000 by Pioneer product.  
The micro processor of PM4200 recognizes a code of the remote control for DVR7000 ,  
Because there is a code of Pioneer product which looks like MD/TAPE code for RC5.

#### [SOLUTION]

Replace MICRO PROCESSOR **IC61** on the **U-COM / TONE & LED PCB**.

#### [NECESSARY PART]

POS.NO    **IC61**    **\*HU100670R**

(FACTORY PART NO. HVIM37531E4FP)

(Delete part : \*HU100530R FACTORY PART NO. BVIANAM1335A)

#### [REMARKS]

The countermeasure apply to this claim only.

The production of PM4200 has been finished.

Approved by    **S.NAGAO**

Written by

<div><b>marantz®</b></div> <div>SERVICE BULLETIN</div>		Date: 17-Jul.-2002	Model: PM4200
		Page: 1/2	REF.NBR: MZ02-009revision
		Subject: Problem with incorrect operation of MUTE.	
Circulation:	Application:		
x for information customer complaint in case of service mandatory .....	See below		
		Int.ref:	

#### [PHENOMENON]

The MUTE LED sometimes blinks and the sounds from output intermit.

#### [CAUSE]

Contact error between the bracket (Pos. No. 30) and the ground of INPUT/AMPLIFIER PCB (Pos. No. 29).

#### [SOLUTION]

**(Revision)**

**Repair work was changed. This work is done without removing a circuit board.**

Contact to the ground certainly by the wire with the lug.

Please refer to the processing figure of the next page and correct.

#### [NECESSARY PART]

The wire with the lug: (MJI Part No. YB00091620 or similar product)

#### [REMARKS]

This improvement has been done in the production line after.

The serial number MZ000149006651 and later. (PM4200/N1B/N2B)



The week code number MZxx0203xxxxxx and later. (PM4200/N1G/N2G)

Approved by **M.KIMURA**

Written by **S.NAGAO**

AQ-19 2 817/additional rule 3 (first edition2002-03-12)

### Processing figure (Part side view)



**Solder the wire to the ground side lead of the R922 or R929**