MODIFICATION

PROBLEM:


You may receive a complaint of the unit producing a very high whistle noise

CAUSE:

The step up transformer for the display circuit is humming

SOLUTION:

- 1. Insert a transformer with more varnish impregnation
- 2. Apply glue to fix the step-up transformer to the main pcb
- 3. Add double sided tape between the cushion at the back of the EL display and the front panel pcb. Please refer to the drawing below



PRODUCTION:

This modification will be implemented in production from serial number: G0ZC52107201



Technical Bulletin

C521BEE

Product: DVD Player Hardware Technical Bulletin:C521BEE-H2005-04

Date: June 27/05 Subject: Laser ribbon cable

Note:

Previous T.B.'s required:

□ YES
■ NO

DESCRIPTION: You may have the complaint that some tracks skip or stops playing altogether.

REASON: The laser pick up connects to the main pc board via a flat ribbon cable and possibly is twisted the wrong way. It maybe getting caught on the fuse holders or other parts. just behind the transport mechanism. See figure 1.

SOLUTION: The ribbon cable needs to be allowed to wrap smoothly as shown in figure 2.

Contact:

NAD Electronics International 633 Granite Court Pickering, ON Canada L1K 3K1

Voice: 905-831-0799 FAX 905-837-6357

www.nadelectronics.com



Technical Bulletin

C521BEE

Product: DVD Player


Hardware Technical Bulletin: C521BEE-H2005-04

Figure 1



INCORRECT

Figure 2



CORRECT