



Q701 HC10141030 STK3122 MK3	Q755, Q756 HT326823A0 2SC2682P (O, R)	Q852 HT113863A0 2SA1386 (O, P, Y)	Q855, Q857, QN06 QN01, QN02, QN05 HT322402A0 2SC2240 (GR, BL)	QN52 HT109701A0 2SA970 GR	QU03, QU04 HT327852C0 2SC2785 (EF, FF)	D802 HE20013290 D5FB20	D853, D854, D857 HD20022030 2SF10C	DU05, DU06 HD30001020 MA1033	QLO1, QLO2, QLO5, QLO6 HF20405100 25K405 N.W.A.C.
Q703, Q704 HT334191Y0 2SC3419Y	Q757, Q758 HT111423A0 2SA1142P (O, R)	Q853 HT332982D0 2SC3298 (O, Y)	QN03, QN04, QN07 HT109702A0 2SA970 (GR, BL)	QU01 HC10009090 NJM2901	QU05 HW10005320 PC847 (4 each Optokopie)	D851, D852 DU01 ~ DU04, DU08, DU09 HD20011050 IS1555	D855, D856 HD20027100 30DF-2	DU07 HD30004020 MA1051	QLO3, QLO4, QLO7, QLO8 HF10115100 25J115 P.W.A.C.
Q705, Q706 HT110152A0 2SA1015 (O, Y)	Q851 HT335193A0 2SC3519 (O, P, Y)	Q854 HT113062D0 2SA1306 (O, Y)	QN51 HC10042050 TA7317P	QU02 HC712301A0 74LS123P	D801 HE20009290 S5VB20	DN01 ~ DN08 HD20014010 ISS81			

"SERVICE INFORMATION IS FOR USE BY QUALIFIED PERSONNEL ONLY - ANY MISADJUSTMENT OR MISALIGNMENT MAY BE TREATED AS A NON-WARRANTY REPAIR BY ANY MARANTZ SERVICE CENTRE -"

NOTE ON SAFETY:
Symbol Δ Fire or electrical shock hazard. Only original parts should be used to replace any part marked with symbol Δ . Any other component substitution (other than original type), may increase risk of fire or electrical shock hazard.

Components and wiring are subject to change for modification without notice.

- Kind of Common Parts**
- RESISTOR**
R*** (1) GD05 - - - 140, Carbon film fixed resistor, $\pm 5\%$ 1/4W
R*** (2) GD05 - - - 160, Carbon film fixed resistor, $\pm 5\%$ 1/6W
- C***** : CERAMIC CAP.
 (1) DD1 - - - - 370, Ceramic condenser, disc type (titan condenser) Temp. coeff. P350 ~ N1000 50V
- C***** : CERAMIC CAP.
 (1) DK16 - - - 300, High dielectric constant ceramic condenser, disc type (titan variable) Temp. chara. 2B4 50V
- ELECTROLY CAP. (E) / FILM CAP. (F)**
E*** : ELECTROLY CAP. (E) / FILM CAP. (F)
 (1) EA - - - - - 10, Electrolytic condenser, one-way lead type, tolerance $\pm 20\%$
 (2) DF15 - - - 350, Plastic film condenser, one-way type, Mylar, $\pm 5\%$ 50V

*In case of ordering the common parts, please establish the correct parts number of 10 figures by the procedure "ASSIGNMENT OF COMMON PARTS CODES"