

marantz® SERVICE BULLETIN		Date: 15-May-2003	Model PS-17SA
		Page: 1/1	REF.NBR: MZ02-019
Circulation:		Subject:	
Application:		Pure Direct mode problem	
x for information customer complaint in case of service mandatory		Sub woofer out problem	
Before MZxxxxxx10xxxx		5ch-STEREO mode problem	
		Int.ref:	

[PHENOMENON]

1. Component output is come up even the unit is in “Pure Direct mode”.
2. No Sub woofer out on the S-Direct mode with DTS or Dolby Digital input.
3. No Center and surround channel out on the 5ch-STEREO mode with Dolby Digital 2ch input.

[SOLUTION]

Replace the Main CPU(QU01) to the new version. (Version No. V011130_1)(Parts No. ***HS330JT3R**)

Replace the Sub CPU(Q609) to the new version. (Version No. V011225_0)(Parts No. ***HS330JT2R**)

[REMARKS]

This improvement has been done in the production after Lot number “11” and later.

The Lot number is mentioned the serial number label on the rear panel.

(ex.MZxxxxxx11xxxx)