

## **Region Setting**

---

---

*The above models are delivered factory set to either R1 or R2 depending on the version. To change the region code to your own area please perform the following,*

- 1. Turn on the unit and remove any discs .*
- 2. Press the “Pause” button on the remote control.*
- 3. Press numeric buttons: 3 1 4 1 5 9*
- 4. VFL shows ‘CODE--‘*
- \*5. Enter the code for your region and press “Pause” button again.*
- 6. Turn off power.*

*\* NOTE: Perform step 5 as quick as possible for unit to accept command.*

*This completes the region setting.*

**Contact:**

**NAD Electronics International**  
**633 Granite Court**  
**Pickering, ON Canada L1K 3K1**  
**Voice: 905-831-0799 FAX 905-837-6357**  
**www.NADelectronics.com**

## **Region Setting**

---

---

*The above models are delivered factory set to either R1 or R2 depending on the version. To change the region code to your own area please perform the following,*

- 1. Turn on the unit and remove any discs .*
  - 2. Press the “Pause” button on the remote control.*
  - 3. Press numeric buttons: 3 1 4 1 5 9*
  - 4. VFL shows ‘CODE--‘*
  - \*5. Enter the code for your region and press “Pause” button again.*
  - 6. Turn off power.*
- \* NOTE: Perform step 5 as quick as possible for unit to accept command.*

*This completes the region setting.*

**Contact:**

**NAD Electronics International**  
**633 Granite Court**  
**Pickering, ON Canada L1K 3K1**  
**Voice: 905-831-0799 FAX 905-837-6357**  
**[www.NADelectronics.com](http://www.NADelectronics.com)**

---

## Software Upgrade

---

***PROBLEM1:** When loading Disney's Atlantis you can't escape from the Main Menu . When playing Star Wars-Episode 1 alien language appears .*

***PROBLEM2:** When playing cd's with music that starts at time 00:00 on the first track you may notice the first ½ second of music is muted.*

---

***CAUSE1:** The current software doesn't recognize the dvd 's menu system.*

***CAUSE2:** The software is muting this part of the cd track.*

---

***SOLUTION:** Upgrade the software with software upgrade Version 0312.This upgrade solves both problems. The software is available from our service website to download to a CD-R. Follow the instructions for upgrading from the upgrade procedure provided.*

---

### ***PRODUCTION:***

This change has been implemented in production from serial number: L23T57103851

---

### **Contact:**

**NAD Electronics International**  
**633 Granite Court**  
**Pickering, ON Canada L1K 3K1**

**Voice: 905-831-0799 FAX 905-837-6357**  
**[www.nadelectronics.com](http://www.nadelectronics.com)**