



**SERVICE BULLETIN
 NO:00005**

MANAGER
 Akira Mori
 2000/07/05

GL
 Seiji Ichikami
 2000/07/04

DESIGN
 Masaoki Yokochi
 2000/05/15

MODELS : TX-DS575

SUBJECT : Change of parts

1. Microprocessor

This model is used the microprocessor of 3 types.

When replace the microprocessor Q7001, refer to the remarks below.

Item	Description	Part No.	Contain of change	Remarks	Application
1	MPD780208GF-045-3BA	22241343		Use item 2 instead of 1. Refer to note below.	MD:1-10600 13001-14600 MP:5001-6900
2	MPD780208GF-047-3BA	22241398	Elimination of 2nd PLL circuit	Use same IC.	MD:10601-13000 14601- MP:1-5000 6901-
3	MPD780208GF-056-3BA	22241419	Improvement of noise when DOLBY.	Use same IC.	From Oct. 1999

Note: When you change the microprocessor from 045-3BA to 047-3BA, remove 2nd PLL circuit and change the setting of A/D,D/A Converter IC Q8501.

