

SONY®

TA-2000F

General Export Model

No. 1
July, 1971

SERVICE MANUAL SUPPLEMENT

Subject: Changes on Model TA-2000F and Service Manual Correction

1. INTRODUCTION

SONY has changed the design of knobs equipped in TA-2000F as given in Table below. Note that the new knob is a serrated type as illustrated. In addition, some transistors are changed in the amplifier section. Notice that there is printing error concerning Idss rank illustration in the service manual. To avoid confusion make the following correction.

2. DESCRIPTION OF THE MODIFICATIONS

2-1. NEW KNOB




TABLE 1. PARTS CHANGED

Description	Parts Number	
	Former	New
VOLUME, TONE(BASS, TREBLE) control knobs, FUNCTION, MODE switch knobs	X-20299-04	X-48049-04
BALANCE control knob, HEADPHONE, METER, FILTER, MIC LEVEL knobs, IMPEDANCE SELECTOR knob	X-20519-03	X-48066-11

Applicable Serial Numbers

500,201 and later

Interchangeability

New and old knobs are not interchangeable.