

CD RECEIVER

# KDC-X990

## SERVICE MANUAL

# KENWOOD


Kenwood Corporation

© 2006-4 CREATED IN JAPAN  
B53-0404-00 (C) 0

### TDF SPARE-PANEL

MODEL	TDF PANEL No.	TDF NAME
KDC-X990	Y33-2350-64	TDF-69DX

CD MECHANISM EXTENSION CORD (24P) : **W05-0934-00**



Refer to the Destination "K1" of service manual XXV-01D's parts list(B53-0296-00) except the following parts.

## PARTS LIST

\* New Parts

Ref. No.	Add	New	Parts No.	Description
<b>KDC-X990</b>				
PA1	3C	*	A64-3965-02	PANEL ASSY
-		*	B64-3427-00	INSTRUCTION MANUAL(ENG.)
-		*	B64-3428-00	INSTRUCTION MANUAL(FRE.)
-		*	B64-3429-00	INSTRUCTION MANUAL(SPA.)
236	2D		E30-6435-05	CORD WITH PINPLUG
-		*	H54-3804-03	ITEM CARTON CASE

Ref. No.	Add	New	Parts No.	Description
<b>SWITCH UNIT(X16-3070-11)</b>				
IC1		*	PL127J60TDI9V7	ROM IC
<b>ELECTRIC UNIT(X34-3560-12)</b>				
C1			C90-6743-05	ELECTRO 3900UF 16WV
Does not include the following parts.				
282				CLEANING CLOTH
CN5				PIN ASSY (X34-3560-12)

This product uses Lead Free solder.

