

marantz® SERVICE BULLETIN		Date: 22-Nov-01	Model: DV12/U1B
		Page: 1/1	REF.NB MZ01-018
Circulation:		Subject:	
Application:		Improvement for inoperable the "PAUSE" and "RANDOM" buttons	
x for information customer complaint in case of service mandatory			
		MZ000136040004 MZ000136040050	

[PHENOMENON]

While CD or Video CD is played after closing the tray by pressing "PLAY", "NEXT", "PREV" or each numeric button. The "PAUSE" and "RANDOM" buttons are not worked.

[SOLUTION]

Replace the microprocessor **QF01** with a new one (**MJI Part No. *HS411KT0R**).

[REMARK]

This improvement has been done in the production line after the serial number "MZ000136040051" and later. The serial number is mentioned on the rear panel.