

marantz® SERVICE BULLETIN		Date: 24-Oct.-2005	Model: ST7001/N1B/N1S
		Page: 1 / 1	REF.NBR: MZ05-038
Level		Application:	
★		See below	
Subject: Correction of the Service Manual, Electrical parts list.			
Int.ref:			

[REASONS]

The parts number for POS. NO **IC300 MAIN PWB** mentioned on the ST7001/N1B/N1S's Service Manual is in correct. (Service Manual page 51)

[CORRECTION PARTS LIST]

OLD NEW	POS. NO.	VERS. COLOR	PART NO. (FOR EUR)	PART NO. (MJI)	PART NAME	DESCRIPTION
OLD	IC300		00D9630226103	00D9630226103	U-PRO	MB90F352PFM-G (128K,4K) LQFP64 Factory code no. J020903520010S
NEW	IC300		90M-HS46BWX0R	90M-HS46BWX0R	U-PRO	MB90F352PFM-G (128K,4K) LQFP64 Factory code no. J020903520010S ST7001 MPxxx

Approved by **N.Sensui** Written by **S.NAGAO**