Pioneer sound.vision.soul

Service Manual

ORDER NO. RRV2795

AUDIO/VIDEO MULTI-CHANNEL RECEIVER VSX-2012-K

THIS MANUAL IS APPLICABLE TO THE FOLLOWING MODEL(S) AND TYPE(S).

Model	Туре	Power Requirement	Remarks
VSX-2012-K	KUXJICA	AC120V	

• This service manual should be used together with the following manual(s):

Model No.	Order No.	Remarks
VSX-45TX/KUXJI/CA	RRV2635	

• For SPECIFICATIONS and PANEL FACILITIES, refer to the operating instructions.

1. CONTRAST OF MISCELLANEOUS PARTS

NOTES: ● Parts marked by "NSP" are generally unavailable because they are not in our Master Spare Parts List.

- The riangle mark found on some component parts indicates the importance of the safety factor of the part. Therefore, when replacing, be sure to use parts of identical designation.
- Screws adjacent to ▼ mark on product are used for disassembly.
- Reference Nos. indicate the pages and Nos. in the service manual for the base model.
- For the applying amount of lubricants or glue, follow the instructions in this manual. (In the case of no amount instructions, apply as you think it appropriate.)

■ CONTRAST TABLE

С

Ε

VSX-2012-K/KUXJICA and VSX-45TX/KUXJI/CA are constructed the same except for the following:

Ref. No. Mark			Part No.		
		Symbol and Description	VSX-45TX /KUXJI/CA	VSX-2012-K /KUXJICA	Remarks
		PACKING SECTION			
P7- 6	NSP	Warranty Card	ARY7007	ARY7045	
P7- 7		Operating Instructions (English)	ARB7257	ARB7297	
P7-16		Packing Case	AHD8060	AHD8243	
		Errata Sheet	ARX7052	Not used	
		REAR PANEL SECTION			
P11-11		Rear Panel	ANC8063	ANC8246	
		FRONT PANEL SECTION			
P15- 8		Door	ANB7277	ANB7275	
P15-25		Pionner Badge	PAN1376	AAN7218	
P15-26		F. Panel	ANB7276	ANB7331	

2

VSX-2012-K